1 ABSTRACT

50. A method for installing a heat exchange pipe loop in a 2 borehole, the method in at least certain aspects, including 3 drilling a borehole with a sonic drill system having a head and 4 casing connected thereto, a drill shoe on a lower end of the casing 5 movable by the sonic drill head to drill the borehole, pumping 6 fluid (e.g., water and drilling fluid) into the casing, out through 7 a lower end of the casing, and up to earth surface in an annular 8 space in the borehole so that drilled material flows to the earth 9 surface, lowering a heat exchange pipe loop down into the casing, 10 introducing grout into the casing around the heat exchange pipe 11 12 loop, and extracting the casing from the borehole.

AMME 010